Morse, Bob

Subject: Seneca PFAS Data Review

Location: 720-543-9770; code 146 733 4676; Password 98244750

Start: Thu 7/23/2020 1:00 PM **End:** Thu 7/23/2020 1:30 PM

Show Time As: Tentative

Recurrence: (none)

Organizer: Badik, Beth

All: This call is scheduled to review preliminary PFAS data (July 2020) at the Fire House and at SEAD 26 at Seneca Army Depot. For your reference, the Final memo (attached) that proposed installation of new wells for this phase of the ESI is attached.

There are two groups of wells for which the exact location is based on data from five initial wells. The wells are listed below.

	Initial Wells	Subsequent wells
Firehouse	MWFH-06, MWFH-07, MWFH-08	MWFH-09/D, MWFH-10/D
SEAD-26	MW26-21 and MW26-22	MW26-23, MW26-24/D, MW26-25

On this call we will review the data from the five initial wells and review recommendations on the locations of the subsequent wells. Figures showing the data and proposed well locations will be provided by Tuesday, July 21.

-- Do not delete or change any of the following text. --

Join Webex Meeting

Meeting number (access code): 146 733 4676 Meeting password: ZVaGHSJ\$365 (98244750 from phones)

Join from a video system or application

Dial 1467334676@parsons.webex.com

You can also dial 173.243.2.68 and enter your meeting number.

Tap to join from a mobile device (attendees only)

+17205439770,,1467334676#98244750# United States Toll 18337521090..1467334676#98244750# United States Toll Free

Some mobile devices may ask attendees to enter a numeric meeting password.

Join by phone

+1 720 543 9770 United States Toll 18337521090 United States Toll Free Global call-in numbers | Toll-free calling restrictions

Additional International Dial-in numbers:

US toll: +1 720 543 9770 US Toll Free: 1 888 413 2357

US/Canada toll free: 1 833 752 1090

Australia toll: +61 292740891
Australia toll free: 1800376740
Bahrain toll free: 80004689
Brazil toll: +55 1147001550
Brazil toll free: 8000474602
France toll: +33 157323256
France toll free: 805540112
Hong Kong toll: +852 30114631
Israel Toll Free: 1809344384
Italy toll: +39 0291483824
Italy toll free: 800931534

Kuwait toll free: 22282968 Luxembourg toll: +35 224871010 Luxembourg toll free: 80024039 Mexico toll free: 18005630653

Oman toll free: 80074215 Qatar toll free: 8000017 Russia toll free: 8003337416

Saudi Arabia toll free: 8008447859 Singapore toll: +65 66221376 Singapore toll free: 8008523608 South Africa toll: +27 214273046 South Africa toll free: 800168140

South Africa toll free: 800168140 South Korea toll: +82 234837034 South Korea toll free: 800077418 Switzerland toll: +41 445118009 Switzerland toll free: 800111199 Turkey toll free: 800448829190

United Arab Emirates toll free: 800035704631

United Kingdom toll: +44 2030246757 United Kingdom toll free: 8000304322

Can't join the meeting?

If you are a host, click here to view host information. IMPORTANT NOTICE: Please note that this Webex service allows audio and other information sent during the session to be recorded, which may be discoverable in a legal matter. By joining this session, you automatically consent to such recordings. If you do not consent to being recorded, discuss your concerns with the host or do not join the session.

NOTICE: This email message and all attachments transmitted with it may contain privileged and confidential information, and information that is protected by, and proprietary to, Parsons Corporation, and is intended solely for the use of the addressee for the specific purpose set forth in this communication. If the reader of this message is not the intended recipient, you are hereby notified that any reading, dissemination, distribution, copying, or other use of this message or its attachments is strictly prohibited, and you should delete this message and all copies and backups thereof. The recipient may not further distribute or use any of the information contained herein without the express written authorization of the sender. If you have received this message in error, or if you have any questions regarding the use of the proprietary information contained therein, please contact the sender of this message immediately, and the sender will provide you with further instructions.